

Subject: Purchasing Buzzer for GLP30.

Date: October 2014

FAO: Kwik Fit GLP30 Installers

FROM: Peter Stevenson

In order to clarify the requirements for ordering the correct item related to the buzzer on the GLP30 please refer to the information below.

When ordering a GLP30 buzzer under warranty the part that is provided is the M22-XAMP beeper and NOT the complete plastic housing for the buzzer.

The housing for the buzzer is not expected to be replaced under warranty and should be ordered as a separate purchased item.

To avoid any confusion:

Ordering Part number	Description	Comments
ROT-60-0098	Peeper for M45	manual reference number E-01-028
	Beeper Seat Code	manual reference number E-01-029

E-01-029
 Ordered as required and NOT provided under warranty.
 When the buzzer fails this part should NOT be discarded.



ROT-60-0098
 Goes inside the plastic seating.
 Provided under warranty and supplied in a labelled M22-Xamp box

Thank you for your assistance in this matter.

